




|   |                                   |   |
|---|-----------------------------------|---|
|  <p>15 Rue des Frères Lumière – BP 136<br/>78374 PLAISIR<br/>FRANCE<br/>Pho : +33(0)1.30.80.81.98<br/>Fax : +33(0)1.30.80.81.99<br/>WEB : www.babbco.fr<br/>E-MAIL : sherwinbabbco@orange.fr</p> | <h1>TECHNICAL<br/>DATA SHEET</h1> | Ref : <b>TDS/NT101B</b><br><br>Page : 2/2<br><br>Rev : 3     Date : 11/09 |
|---|-----------------------------------|---|

## **INSTRUCTIONS :**

First of all, eliminate most of the excess off PRT23E penetrant, by wiping the part with clean, dry cloths, then wipe with a clean cloth slightly moistered with NT101B, and wipe again with a clean dry cloth to eliminate the last traces of penetrant.

Do not spray directly NT101B on the part.

Apply immediately after a thin layer of RT71 (see technical data sheet)

## **HEALTH AND SAFETY :** refer to MSDS.

*The information given herein is given in good faith to our customers for the sole purpose of assisting them in the use of the products. The document contains no formal or implicit guarantee regarding its use.*

*Babb Co cannot be held responsible for damages of any nature resulting from information provided in this document. In addition, none of the information which the document contains should be interpreted as a recommendation for the use of the products which would infringe the protected rights of industrial property.*